


PACKING LIST

Frame	pcs
Pre-assembled frame set	
Outer pipe	2
Conection pipe	2
Control box	1
Motor	1
Aluminum extension set	1
Cable clamp	7
Screw for Connection pipe, M8x12mm	8
Screw for Control box, M4x6mm	2
Column	2
End pipe	2
Feet	2
Rubber washer	18
Accessory	
Handset	1
AC cable	1
Hardware	
screw for Column, M6x16mm	8
Screw for Feet, M10x16mm	8
Screw for Handset, Ø4x22mm	2
Screw for Tabletop, Ø5x20mm	18
Allen key for Feet, 5mm	1
Allen key for Column, 4mm	1
Allen key for Aluminum extension set, 2mm	1
TIGHTENING TORQUE	
Tailstock	Maximum 6Nm
Screw for Column	15-20Nm
Screw for Feet and Tabletop	Maximum 10Nm
Screw for Handset	< 6Nm
Make sure all screws are tightened, also after a period of use!	
REST THE DESK BEFORE USE	
Press both up and down buttons at the same time for 3 seconds. Continue pressing the buttons until both columns are in lowest position. When finish reset, the control box makes a sound and the buttons can be released. Now the system is operational.	


WARNING

Carefully arrange all the cables not to be damaged by tabletop screws.


Step 1




Step 2




Step 3




Step 4




Step 5




Step 6




Step 7




Step 8




Step 9




Step 10



Step 11



Step 12



Step 13

